



BIOS Update Release Notes

PRODUCTS: CD1IV128MK (Standard BIOS)

BIOS Version 0038 - MKKBLi5v.86A.0038.2019.0813.1700

About This Release:

- Date: August 13, 2019
- ROM Image Checksum: 0x7121
- ME Firmware: 11.8.60.3561
- EC Firmware: 6.6D
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
 - Option ROM: 9.0.1060
 - UEFI Driver: 9.0.1084
- AHCI Code: AHCI_14
- Supported Flash Devices:
 - Winbond W25Q128FVPIG 16MB
 - MACRONIX MX25L12845EZNI 16MB
- Microcode Updates included in .ROM File:
 - MC0806E9_000000B4.mcb
- Additional Microcode Updates included only in .BIO File:
 - MC0806E9_000000B4.mcb

New Fixes/Features:

- Added Realtek PXE option ROM.
- Updated BIOS for security fixes.
- Updated BIOS code for BIOS recovery with USB flash drive.

BIOS Version 0037 - MKKBLi5v.86A.0037.2019.0531.2257

About This Release:

- Date: May 31, 2019
- ROM Image Checksum: 0x67DA
- ME Firmware: 11.8.60.3561.
- EC Firmware: 6.6D
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
 - Option ROM: 9.0.1060
 - UEFI Driver: 9.0.1084
- AHCI Code: AHCI_14
- Supported Flash Devices:
 - Winbond W25Q128FVPIG 16MB
 - MACRONIX MX25L12845EZNI 16MB
- Microcode Updates included in .ROM File:
 - MC0806E9_000000B4.mcb
- Additional Microcode Updates included only in .BIO File:

New Fixes/Features:

- Updated BIOS and CPU microcode for security fixes.

BIOS Version 0036 - MKKBLi5v.86A.0036.2019.0318.1105

About This Release:

- Date: March 18, 2019
- ME Firmware: 11.8.60.3561.
- EC Firmware: 6.6D
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
 - Option ROM: 9.0.1060
 - UEFI Driver: 9.0.1084
- AHCI Code: AHCI_14

New Fixes/Features:

- Updated CPU microcode to MC0806E9_0000009A.
- Updated Intel® ME firmware to version 11.8.60.3561.
- Modified BIOS code for security fixes.
- Updated support for Windows 10 RS5.
- Updated VBIOS to version 9.0.1060.
- Updated graphics UEFI driver to version 9.0.1084.

Known Errata:

- Due to the Intel® ME firmware update in BIOS version 0036, you can't downgrade to version 0034 or earlier.

BIOS Version 0034 - MKKBLi5v.86A.0034.2018.1123.1230

About This Release:

- Date: November 23, 2018
- ME Firmware: 11.8.50.3460
- EC Firmware: 6.6D
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics
 - Option ROM: 9.0.1051
 - UEFI Driver: 9.0.1075
- AHCI Code: AHCI_14

New Fixes/Features:

- Updated setup items (F9 & CTRL-P) layout.

BIOS Version 0033 - MKKBLi5v.86A.0033.2018.0926.1510

About This Release:

- Date: September 26, 2018
- ME Firmware: 11.8.50.3460
- EC Firmware: 6.6D
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010

- Integrated Graphics:
 - Option ROM: 9.0.1051
 - UEFI Driver: 9.0.1075
- AHCI Code: AHCI_14

New Fixes/Features:

- Updated Intel Integrator Toolkit regarding configuring of Setup items.

BIOS Version 0032 - MKKBLi5v.86A.0032.2018.0718.1545

About This Release:

- Date: July 18, 2018
- ME Firmware: 11.8.50.3460
- EC Firmware: 6.6D
- Memory Reference Code: Based on 3.2.0
- MEBx Revision: 11.0.0.0010
- Integrated Graphics:
 - Option ROM: 9.0.1051
 - UEFI Driver: 9.0.1075
- AHCI Code: AHCI_14

New Fixes/Features:

- Updated CPU Microcode (Security Advisory-00115).
- Added BIOS Option, "Boot USB Devices First".

BIOS Version 0031 - MKKBLi5v.86A2018.0601.1349

About This Release:

- Date: June 1, 2018
- ME Firmware: 11.8.50.3460
- EC Firmware: 6.6D
- MEBx Revision: 11.0.0.0010
- Integrated Graphics:
 - Option ROM: 9.0.1051
 - UEFI Driver: 9.0.1075
- AHCI Code: AHCI_14

New Fixes/Features:

- Updated EC firmware to version 6.6D.
- Added security enhancements.

BIOS Version 0030 - MKKBLi5v.86A.0030.2018.0328.1225

About This Release:

- Date: March 28, 2018
- ME Firmware: 11.8.50.3460
- EC Firmware: 6.6C
- MEBx Code: 11.0.0.0010
- Integrated Graphics:
 - Option ROM: 9.0.1051
 - UEFI Driver: 9.0.1075
- AHCI Code: AHCI_14

New Fixes/Features:

- Updated Intel® ME firmware to version 11.5.50.3460.
- Updated the GOP version.
- Updated EC firmware to version 6.6C.
- Due to a security enhancement, the BIOS cannot be downgraded to any version older than version 0030.

BIOS Version 0028 - MKKBLi5v.86A.0028.2018.0226.1712

About This Release:

- Date: February 26, 2018
- ME Firmware: 11.8.50.3425
- EC Firmware: 6.6A
- MEBx Code: 11.0.0.0010
- Integrated Graphics:
 - Option ROM: 9.0.1051
 - UEFI Driver: 9.0.1066
- AHCI Code: AHCI_14

New Fixes/Features:

- Updated CPU Microcode (Security Advisory-00088)
- Updated EC firmware to version 6.6A.
- Fixed issue with disabling eMMC controller.
- Fixed issue with POST hotkeys.
- Fixed issue with Remote Secure Erase with Intel® AMT.
- Modified processor max speed.
- Added HDD password functionality.
- Modified setup item ACPI S3 to depend on ECRAM.
- Fixed issue when USB Boot is set to disabled.

BIOS Version 0024 - MKKBLi5v.86A.0024.2017.1113.1052

About This Release:

- Date: November 13, 2017
- ME Firmware: 11.8.50.3425
- EC Firmware: 6.5A
- MEBx Code: 11.0.0.0010
- Integrated Graphics:
 - Option ROM: 9.0.1051
 - UEFI Driver: 9.0.1066

New Fixes/Features:

- Initial production BIOS release.

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a

particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, lifesaving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.
Copyright (c) 2017 Intel Corporation.